

MSD HAZARDOUS MATERIALS ORDINANCE RELATED INCIDENTS
JUNE 2025 RGM

DATE	INCIDENT ID	INCIDENT COMMAND	RESPONSIBLE PARTY	LOCATION	ROOT CAUSE AND/OR FINDINGS	MATERIAL	HAZMAT LEVEL	MITIGATION/REMEDATION EFFORTS	ENFORCEMENT ACTION	CORRECTIVE ACTIONS & PREVENTION
5/8/2025	25ER1073	LOU FD / STMAFD	LOUISVILLE/JEF COUNTY METRO	595 N HUBBARDS LN WINDY HILLS KY	Approximately 2 cups of white powder found in shipping container. Mass Spectrometry utilized to identify substance.	Hexamethylcycltrisiloxane	1	East District Public Works disposed of material.	NFAN	LMPHW responsible for remediation and issued clean up orders.
5/14/2025	25ER1081	LOU FD	SPEEDWAY	470 CHICOPEE AVE LOUISVILLE KY	Approximately 46 gallons of gasoline released from spill.	Gasoline	0	FD used firewater to control Lower Explosive Limit (LEL). Some material discharged to MSD treatment center. Site remediated and material recovered from catch basin.	NFAN	LMPHW responsible for remediation. Speedway contracted Pecco for cleanup.
5/19/2025	25ER1082	OKO FD	MSD	7201 PRESTON HWY LOUISVILLE KY	Approximately 1 quart of motor oil released to environment from skid-steer rollover.	Oil Mixture	0	Material recovered by absorbent boom and disposed of by MSD.	NFAN	MSD responsible for remediation.
6/3/2025	25ER1085	PRP FD	Rohm and Haas Chemicals, LLC	4300 CAMP GROUND RD. LOUISVILLE KY	Approximately 10 gallons of Butyl Acrylate spilled from tanker trailer relief valve.	Butyl Acrylate	0	Material evaporated into atmosphere upon release. Dry mitigant that was initially placed and disposed of by Rohm and Haas.	NFAN	Pressure Safety Valve (PSV) was repaired.
6/4/2025	25ER1087	PRP FD	CHARTERS LLC	3801 BELLS LN LOUISVILLE KY	Fire suppression water from structure fire.	Fire Water	1	N/A	NFAN	N/A
6/7/2025	25ER1089	ANC-MID FD	Ford Motor Co.	3001 CHAMBERLAIN LN LOUISVILLE KY	Approximately 30 gallons of hydraulic fluid released with less than 1 gallon entering a storm drain. Incident result of loose hose caught on tire and separated from vehicle.	Hydraulic Fluid	1	Booms and dry mitigant deployed. Used mitigant captured by Ford Motor Co. and disposed of. Storm conveyance equipped with structural Best Management Practices (BMP)/ Oil-Water Separator (OWS).	NFAN	LMPHW responsible for remediation. Ford verified with truck company/contractor that pre-inspections required before leaving facility.

ABBREVIATIONS	
ANC-MID FD	ANCHORAGE/MIDDLETOWN FIRE DEPARTMENTS
APCD	AIR POLLUTION CONDRTROL DISTRICT
CSS	COMBINED SEWER SYSTEM
EMA	EMERGENCY MANAGEMENT AGENCY
FC FD	FERN CREEK FIRE DEPARTMENT
FD	FIRE DEPARTMENT
FF	FIRE FIGHTING
HMO	HAZARDOUS MATERIALS INCIDENT
IBC	INTERMEDIATE BULK CONTAINERS
IWD	INDUSTRIAL WASTE DEPARTMENT
J-TOWN FD	JEFFERSONTOWN FIRE DEPARTMENT
KYDOW	KENTUCKY DIVISION OF WATER
KYERB	KENTUCKY EMERGENCY RESPONSE BRANCH
KYERT	KENTUCKY EMERGENCY RESPONSE TEAM
LMPHW	LOUISVILLE METRO DEPARTMENT OF HEALTH & WELLNESS
LOU FD	LOUISVILLE FIRE DEPARTMENT
MSD	LOUISVILLE METROPOLITAN SEWER DISTRICT
MS4	MUNICIPAL SEPARATE STORM SEWER SYSTEM
MVA	MOTOR VEHICLE ACCIDENT
N/A	NOT APPLICABLE
NFAN	NO FURTHER ACTION NEEDED
NOV	NOTICE OF VIOLATION
OKOFD	OKOLONA FIRE DEPARTMENT
RQ	REPORTABLE QUANTITY
PRP FD	PLEASURE RIDGE FIRE DEPARTMENT
RGM	RESPONSE GROUP MEETING
STMA FD	ST. MATTHEWS FIRED DEPARTMENT

Cases are released after they are reviewed in monthly Response Group Meetings (RGM) involving MSD, EMA, LMPHW, and APCD.
Cases related to hazardous materials, including declared hazmat levels by fire departments, are listed but may not meet the definition of a hazardous materials incident per the HMO.