

MSD HAZARDOUS MATERIALS ORDINANCE RELATED INCIDENTS
July 2026 RGM

DATE	INCIDENT ID	INCIDENT COMMAND	RESPONSIBLE PARTY	LOCATION	ROOT CAUSE AND/OR FINDINGS	MATERIAL	HAZMAT LEVEL	MITIGATION/REMEDATION EFFORTS	ENFORCEMENT ACTION	CORRECTIVE ACTIONS & PREVENTION
6/17/2026	26ER1106	OKOL FD	MVA	Intersection I-65 North & I-65 Ramp LOUISVILLE KY	Approximately 200 gallons of diesel fuel released due to MVA. No waterway or MSD assets affected.	Diesel Fuel	1	FD deployed hazmat pool to contain material. LMPHW responsible for remediation efforts.	NFAN	N/A (MVA)
6/22/2026	26ER1107	STMA FD	MVA	Intersection I-71 South & I-264 Ramp LOUISVILLE KY	Approximately 150 gallons of diesel fuel released due to MVA. MS4 & Longview Creek affected.	Diesel Fuel	0	MSD deployed absorbent booms.	NFAN	N/A (MVA)
6/23/2026	26ER1108	PRP FD	Byerly Ford	4027 Dixie HWY LOUISVILLE KY	Unknown amount of fire suppression water and vehicle fluids released due to fire. MS4 affected.	Fire Water / Vehicle Fluids	0	MSD deployed absorbent boom.	NFAN	N/A (fire suppression)
6/26/2026	26ER1110	LOU FD	MVA	4107 Northwestern Parkway LOUISVILLE KY	Approximately 60 gallons of diesel fuel released due to MVA. Ohio River affected.	Diesel Fuel	1	Mitigation not possible due to direct discharge to Ohio River.	NFAN	N/A (MVA)
7/1/2026	26ER1112	PRP FD	Resident	6705 Pendleton Road LOUISVILLE KY	1-3 pints of laundry detergent released from spill. No waterway or MSD assets affected.	Detergent	0	Area remediated through excavation, neutralization, and disposal with LMPHW oversight.	NFAN	N/A (non-haz, & no impacts)
7/6/2026	26ER1114	LOU FD	MSD	350 Adams Street LOUISVILLE KY	High LEL detected in CSS.	Unknown	0	FD flushed system to reduce LEL.	NFAN	N/A (undetermined source)
7/7/2026	26ER1116	LOU FD	MSD	2121 W. Lee St. LOUISVILLE KY	Unknown amount of used motor oil dumped in catch basin	Oil	0	MSD deployed absorbent booms.	NFAN	N/A (responsible party unknown)
7/8/2026	26ER1119	LOU FD	Reynolds	2827 Hale Ave. LOUISVILLE KY	Approximately 1200 gallons of hydraulic fluid released due to pipe failure. No waterway or MSD assets affected; contained to gravel.	Hydraulic Fluid	0	Some material contained in temporary vessel placed under leak. Impacted gravel excavated and disposed of. LMPHW responsible for remediation efforts.	NFAN	Piping insulation to be removed from outdoor above-ground piping and inspection performed. Industry researching low pressure alarm.

ABBREVIATIONS	
ANC-MID FD	ANCHORAGE/MIDDLETOWN FIRE DEPARTMENTS
APCD	AIR POLLUTION CONDTROL DISTRICT
CSS	COMBINED SEWER SYSTEM
EMA	EMERGENCY MANAGEMENT AGENCY
FC FD	FERN CREEK FIRE DEPARTMENT
FCN	FIELD CORRECTION NOTICE
FD	FIRE DEPARTMENT
FRDLFD	FAIRDALE FIRE DEPARTMENT
FF	FIRE FIGHTING
HMO	HAZARDOUS MATERIALS INCIDENT
IBC	INTERMEDIATE BULK CONTAINERS
IWD	INDUSTRIAL WASTE DEPARTMENT
J-TOWN FD	JEFFERSONTOWN FIRE DEPARTMENT
KYDOW	KENTUCKY DIVISION OF WATER
KYERB	KENTUCKY EMERGENCY RESPONSE BRANCH
KYERT	KENTUCKY EMERGENCY RESPONSE TEAM
LMPHW	LOUISVILLE METRO DEPARTMENT OF HEALTH & WELLNESS
LOU FD	LOUISVILLE FIRE DEPARTMENT
MSD	LOUISVILLE METROPOLITAN SEWER DISTRICT
MS4	MUNICIPAL SEPARATE STORM SEWER SYSTEM
MVA	MOTOR VEHICLE ACCIDENT
N/A	NOT APPLICABLE
NFAN	NO FURTHER ACTION NEEDED
NOV	NOTICE OF VIOLATION
OKOFD	OKOLONA FIRE DEPARTMENT
RQ	REPORTABLE QUANTITY
PRP FD	PLEASURE RIDGE FIRE DEPARTMENT
PRR	PRELIMINARY RESPONSE REPORT
RAAFR	REG Airport Auth/Air/Fire/Rescue
RGM	RESPONSE GROUP MEETING
STMA FD	ST. MATTHEWS FIRED DEPARTMENT

Cases are released after investigation is completed and reviewed in monthly Response Group Meetings (RGM) involving MSD, EMA, LMPHW, and APCD.
Cases related to hazardous materials, including declared hazmat levels by fire departments, are listed but may not meet the definition of a hazardous materials incident per the HMO.