

MSD HAZARDOUS MATERIALS ORDINANCE RELATED INCIDENTS
February 2026 RGM

DATE	INCIDENT ID	INCIDENT COMMAND	RESPONSIBLE PARTY	LOCATION	ROOT CAUSE AND/OR FINDINGS	MATERIAL	HAZMAT LEVEL	MITIGATION/REMEDATION EFFORTS	ENFORCEMENT ACTION	CORRECTIVE ACTIONS & PREVENTION
11/19/25	25ER1188	PRP FD	K & I Terminal	3320 WOODLAND DR R LOUISVILLE KY	Approximately 110 gallons of oily substance found to be leaking from abandoned plastic drums. No waterways or sewers impacted.	Oil/Unknown	0	Absorbent booms placed downstream in anticipation of rain. LMPHW responsible for remediation efforts.	NFAN; no responsible party identified	N/A; no responsible party identified.
1/7/26	26ER1003	ANC-MID-FD	Abandoned Boat	6491 MARINA DR LOUISVILLE KY	Oily sheen found around abandoned boat. Ohio River impacted.	Hydrocarbons	0	USCG and KYERT responsible for remediation efforts.	NFAN; no responsible party identified	N/A; no responsible party identified.
1/12/26	26ER1005	PRP FD	Rohm & Haas	4300 CAMP GROUND RD LOUISVILLE KY	Approximately 1,096 lbs. of Butyl Acrylate was spilled during loading resulting from seal becoming unsealed. Material entered private chemical sewer.	Butyl Acrylate	1	Majority of material recovered, drummed, and sent offsite for disposal. Residuals discharged to MSD through sewer. LMPHW responsible for remediation efforts.	NFAN; notification made	Facility now requires second person to verify that snorkel loading arm is correct, procedure revision, and reducing the flowrate during initial loading.
1/14/26	26ER1006	PRP FD	MSD	3050 COMMERCE CENTER PL LOUISVILLE KY	Approximately 2 gallons of diesel fuel spilled a fuel island. No stormwater conveyance or sewers affected.	Diesel Fuel	0	MSD applied dry absorbent and disposed of used mitigant.	NFAN; Non-RQ	Implement guidelines to monitor pump at all times while fueling.
1/14/26	26ER1007	OKOL FD	Ford LAP	2000 FERN VALLEY RD LOUISVILLE KY	Unknown amount of hydraulic oil entered catch basin and discharged to Northern Ditch.	Hydrocarbons	0	Industry collected remaining material on site and treated at on site WWTP and Oil/Water Separator. KYERT responsible for remediation efforts.	NOV	Industry requiring contractors to perform more frequent inspections. Structural BMPs preventing discharge to waterway will be maintained/replaced.
1/14/26	26ER1008	PRP FD	Algood	7401 TRADE PORT DR LOUISVILLE KY	Less than 1 gallon of anhydrous ammonia released into atmosphere due to failed seal.	Ammonia	1	N/A; air release	NFAN; Non-RQ	Compressors will be inspected every shift. Fault has been corrected.
1/15/26	26ER1009	OKOL FD	Ford LAP	2000 FERN VALLEY RD LOUISVILLE KY	Approximately 130 gallons of diesel fuel released from punctured saddle tank. No waterways or conveyances impacted.	Diesel Fuel	1	Absorbent booms, pads and mitigant placed. Remediation contractors cleaned site. KYERT and LMPHW responsible for cleanup efforts.	NFAN; notification made	N/A; MVA
1/18/26	26ER1013	PRP FD	Eckart	4101 CAMP GROUND RD LOUISVILLE KY	Approximately 1,295 gallons of D60 mineral spirits released into the environment due to pump seal failure.	Mineral Spirits	1	Material was recovered from secondary containment for reuse.	NOV & Administrative Fine	An automatic timer will be added to process to shutoff after 30 minutes. Design of flow back piping will be reviewed.
1/27/26	26ER1018	PRP FD	Resident	6203 BROXIE CT LOUISVILLE KY	An unknown amount of natural gas was released do to gas line failure.	Natural Gas	1	N/A; air release	NFAN; notification made	N/A
2/2/26	26ER1020	LOU FD	Humana	300 S 1ST ST LOUISVILLE KY	Approximately 10 gallons of gasoline released to the environment from work vehicle due to vandalism. No conveyance affected.	Gasoline	0	Material was recovered and disposed of by PETRO Towery. LMPHW responsible for remediation efforts.	NFAN; Non-RQ	N/A; no responsible party identified.
2/9/25	26ER1022	PRP FD	Bakelite	6200 CAMP GROUND RD LOUISVILLE KY	Approximately 625 gallons of 50% sodium hydroxide solution was released into environment due to valve freezing in the open position.	Sodium Hydroxide	1	Material held in secondary containment and pumped to totes.	N/A; notification made	Replacement of valve.

ABBREVIATIONS

ANC-MID FD	ANCHORAGE/MIDDLETOWN FIRE DEPARTMENTS
APCD	AIR POLLUTION CONDITROL DISTRICT
CSS	COMBINED SEWER SYSTEM
EMA	EMERGENCY MANAGEMENT AGENCY
FC FD	FERN CREEK FIRE DEPARTMENT
FCN	FIELD CORRECTION NOTICE
FD	FIRE DEPARTMENT
FRDLFD	FAIRDALE FIRE DEPARTMENT
FF	FIRE FIGHTING
HMO	HAZARDOUS MATERIALS INCIDENT
IBC	INTERMEDIATE BULK CONTAINERS
IWD	INDUSTRIAL WASTE DEPARTMENT
J-TOWN FD	JEFFERSONTOWN FIRE DEPARTMENT
KYDOW	KENTUCKY DIVISION OF WATER
KYERB	KENTUCKY EMERGENCY RESPONSE BRANCH
KYERT	KENTUCKY EMERGENCY RESPONSE TEAM
LMPHW	LOUISVILLE METRO DEPARTMENT OF HEALTH & WELLNESS
LOU FD	LOUISVILLE FIRE DEPARTMENT
MSD	LOUISVILLE METROPOLITAN SEWER DISTRICT
MS4	MUNICIPAL SEPARATE STORM SEWER SYSTEM
MVA	MOTOR VEHICLE ACCIDENT
N/A	NOT APPLICABLE
NFAN	NO FURTHER ACTION NEEDED
NOV	NOTICE OF VIOLATION
OKOFD	OKOLONA FIRE DEPARTMENT
RQ	REPORTABLE QUANTITY
PRP FD	PLEASURE RIDGE FIRE DEPARTMENT
RAAFR	REG Airport Auth/Air/Fire/Rescue
RGM	RESPONSE GROUP MEETING
STMA FD	ST. MATTHEWS FIRED DEPARTMENT

Cases are released after they are reviewed in monthly Response Group Meetings (RGM) involving MSD, EMA, LMPHW, and APCD.
Cases related to hazardous materials, including declared hazmat levels by fire departments, are listed but may not meet the definition of a hazardous materials incident per the HMO.