

MSD HAZARDOUS MATERIALS ORDINANCE RELATED INCIDENTS
January 2026 RGM

DATE	INCIDENT ID	INCIDENT COMMAND	RESPONSIBLE PARTY	LOCATION	ROOT CAUSE AND/OR FINDINGS	MATERIAL	HAZMAT* LEVEL	MITIGATION/REMEDATION EFFORTS	ENFORCEMENT ACTION	CORRECTIVE ACTIONS & PREVENTION
12/14/2025	25ER1197	LOU FD	UPS Worldport Freight	4525 CRITTENDEN DR LOUISVILLE KY	Approximately 87 gallons of Jet-X 2% FF Foam was released in hangar and CSS due to software failure.	Jet-X-Foam	0	UPS vacuumed and clean retention area.	NFAN	Company looking into software alternatives.
12/16/2025	25ER1198	LOU FD	Resident	5314 DEVERS AVE LOUISVILLE KY	An unknown amount of used motor oil was discarded into a CSS catch basin.	Motor Oil	0	MSD Contracted Clean Harbors for remediation.	NFAN	N/A (Responsible party unidentified).
12/21/2025	25ER1199	FERN FD	LWC	5106 YAUPON LN LOUISVILLE KY	Approximately 248 lbs. of gasoline and 150 lbs. of hydraulic fluid was released during vehicle fire (gas generator). Material did affect waterway.	Gasoline	1	FD and MSD placed absorbent booms. LMPHW responsible for remediation efforts.	NFAN	N/A (MVA)
12/26/2025	25ER1205	LOU FD	None	336 INVERNESS AVE LOUISVILLE KY	An unknown amount of used motor oil was discarded into a MS4 catch basin.	Motor Oil	0	MSD Contracted Clean Harbors for remediation.	NFAN	N/A (Responsible party unidentified).
12/30/2025	25ER1206	PRP FD	MSD	3050 COMMERCE CENTER PL LOUISVILLE KY	Approximately 6 gallons of diesel fuel was spilled during refueling at MSD fuel island. No sewer/waterway impacted.	Diesel Fuel	0	MSD applied dry mitigant and cleaned site.	NFAN	N/A (Not a RQ)
12/30/2025	25ER1207	OKOL FD	Zeon	4100 BELLS LN LOUISVILLE KY	Approximately 342 lbs. of 1,3-butadiene was released into atmosphere. Cause of incident is unknown.	Butadiene	1	N/A (air release)	NFAN	Dependent on discovery of cause.
1/1/2026	26ER1000	PRP FD	Zeon	4100 BELLS LN LOUISVILLE KY	Approximately 72 lbs. of cumene hydroperoxide was released due to a leaking valve.	G-11-Trigonox	1	Zeon recovered material for disposal.	NFAN	Policy in place to inspect process lines for leaking equipment.
1/5/2026	26ER1002	PRP FD	MSD	3050 COMMERCE CENTER PL LOUISVILLE KY	Approximately 25 lbs. of gasoline was spilled during refueling at MSD fuel island. No sewer/waterway impacted.	Gasoline	0	MSD applied dry mitigant and cleaned site.	NFAN	N/A (Not a RQ)

ABBREVIATIONS

ANC-MID FD	ANCHORAGE/MIDDLETOWN FIRE DEPARTMENTS
APCD	AIR POLLUTION CONDTROL DISTRICT
CSS	COMBINED SEWER SYSTEM
EMA	EMERGENCY MANAGEMENT AGENCY
FC FD	FERN CREEK FIRE DEPARTMENT
FCN	FIELD CORRECTION NOTICE
FD	FIRE DEPARTMENT
FF	FIRE FIGHTING/FIRE FIGHTER(S)
FRDLFD	FAIRDALE FIRE DEPARTMENT
HMO	HAZARDOUS MATERIALS INCIDENT
IBC	INTERMEDIATE BULK CONTAINERS
IWD	INDUSTRIAL WASTE DEPARTMENT
J-TOWN FD	JEFFERSONTOWN FIRE DEPARTMENT
KYDOW	KENTUCKY DIVISION OF WATER
KYERB	KENTUCKY EMERGENCY RESPONSE BRANCH
KYERT	KENTUCKY EMERGENCY RESPONSE TEAM
LMPHW	LOUISVILLE METRO DEPARTMENT OF HEALTH & WELLNESS
LOU FD	LOUISVILLE FIRE DEPARTMENT
LWC	LOUISVILLE WATER COMPANY
MS4	MUNICIPAL SEPARATE STORM SEWER SYSTEM
MSD	LOUISVILLE METROPOLITAN SEWER DISTRICT
MVA	MOTOR VEHICLE ACCIDENT
N/A	NOT APPLICABLE
NFAN	NO FURTHER ACTION NEEDED
NOV	NOTICE OF VIOLATION
OKOFD	OKOLONA FIRE DEPARTMENT
PRP FD	PLEASURE RIDGE FIRE DEPARTMENT
RAAFR	REG Airport Auth/Air/Fire/Rescue
RGM	RESPONSE GROUP MEETING
RQ	REPORTABLE QUANTITY
STMA FD	ST. MATTHEWS FIRED DEPARTMENT

*0 denotes an incident that was not declared a hazardous materials incident level by FD.
Hazardous Materials Incident levels are determined by FD and may not correspond to the definition of a Hazardous Materials Incident per the HMO.
Cases are released after investigation is complete and have been reviewed in monthly Response Group Meetings (RGM) involving MSD, EMA, LMPHW, and APCD.